

DATE 9/13/82

SSC Service Bulletin

no. 82-272

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: MCL60 PA DECK, ALL RANGES

PRODUCTION CHANGES:


To aid in production assembly and field service of the MCL60 PA the following changes have gone into effect as of 9/82:

On Range A & B PA decks capacitors C105, C109, and C115 have been deleted.

On Range C PA decks capacitor C115 has been deleted.

On all PA deck ranges capacitor C114 has been changed to a .01mf NPO ceramic chip cap (Regency Part # 1540-0103-683).


TECHNICAL SERVICE DEPARTMENT
REGENCY COMMUNICATIONS, INC.



*NOTE

POST SEPT. 1982 PRODUCTION:—
DELETE C105, C109, C115.
CHANGE C114 TO .01 μ F CERAMIC CHIP (NPO)

A & B RANGE



C RANGE

*NOTE

POST SEPT. 1982 PRODUCTION:
DELETE C115.
CHANGE C114 TO .01 μ F CERAMIC CHIP (NPO)